



1/4


FIG. 1



Configuration 1



Configuration 2



$$V(t) = K1 \cdot \cos(w \cdot t) + K2$$

2/4

# PHASE-LOCKED LOOP






FIG. 3

Configuration 2



Configuration 1



3/4




FIG. 4

FIG. 5




FIG. 6

